





1. 60.

















Fig. 3F











































Fig. 11A








Fig. 11E



Fig. 12A




Fig.12B




Fig.12C




Fig.12D






Fig. 13








Fig. 15




Fig.16A




Fig. 16B




Fig.17




Fig. 18




Fig.19

REACTION RATE OF RESIN SHEET








Fig. 20












Fig. 23




Fig. 24A

2

3

599

5 598




Fig. 25




Fig. 26








Fig. 27












Fig. 29A




Fig. 29B




Fig. 29C




Fig. 29D




Fig. 30









Fig. 31























Fig. 34




Fig. 35




Fig. 36




Fig.37A









Fig.37B

































Fig. 44C 502 505 AIR PRESSURE · 🛂






Fig. 46A




Fig. 46B








Fig. 46C












Fig. 48E

Fig.49A




Fig.49B




Fig.49C




Fig.49D






Fig.50








Fig. 51B




Fig. 52

100




Fig.53




Fig. 54

REACTION RATE OF RESIN SHEET




Fig. 55




Fig. 56A





Fig. 56C






Fig. 56D




Fig. 57




Fig. 58




Fig. 59A




Fig. 59B





Fig. 60












Fig. 62












Fig. 64A




Fig. 64B




Fig. 64C




Fig. 64D




Fig. 65




Fig. 66









Fig. 67A





















Fig. 69



531 Fre !

Fig. 70 670 671 674 673 670 672